SAND

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

SODA ASH	0-2 POUNDS
MAX BORE OR MAXGEL	2-3 BAGS
SAND COMMANDER	1 TUB
HDD LUBE	1 JUG

TOOLING:

FLUTED REAMER

FLYCUTTER

*MIX PRODUCTS IN THE ORDER SHOWN ABOVE (POWDERS FIRST THROUGH THE HOPPER & LIQUIDS LAST THROUGH THE TOP OF THE TANK.

CLAY/REACTIVE CLAY

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

CLAY COMMANDER	1 TUB
HDD LUBE	1 JUG

ALTERNATVE CLAY MIX:

SODA ASH	0-2 POUNDS
MAXBORE OR MAXGEL	1 1/2 - 2 BAGS
SAND COMMANDER	1 TUB
HDD LUBE	1 JUG

* IF NEEDED FOR REACTIVE CLAY: 1 JUG OF CLAY BOMB
* ADD CLAY BOMB & HDD LUBE AFTER BENTONITE IS YIELDED.

TOOLING:

MIX MASTER

BEAVER TAIL

*MIX PRODUCTS IN THE ORDER SHOWN ABOVE (POWDERS FIRST THROUGH THE HOPPER & LIQUIDS LAST THROUGH THE TOP OF THE TANK.

ROCK/GRAVEL/SANDSTONE

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

SODA ASH	0-2 POUNDS
MAX BORE OR GEL	2-3 BAGS
COBBLE COMMANDER	1 TUB
HDD LUBE	1 JUG

IF HEALTHIER FILTER

CAKE IS NEEDED FOR

FLUID LOSS:

SAND COMMANDER	1/2 TUB

*MIX PRODUCTS IN THE ORDER SHOWN ABOVE (POWDERS FIRST THROUGH THE HOPPER & LIQUIDS LAST THROUGH THE TOP OF THE TANK.