



RIGHT TURN SUPPLY

DRY MIXING CHART

PRODUCT BREAKDOWN



SAND

GENERAL MIXING INSTRUCTIONS | PER 500 GAL TANKS

SODA ASH	2 POUNDS
MAX BORE OR MAXGEL	2-3 BAGS
COBBLE COMMANDER	1 TUB
HDD LUBE	1 JUG
PAC L FORCE	2 POUNDS

TOOLING:

FLUTED REAMER

FLYCUTTER

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



CLAY/REACTIVE CLAY

GENERAL MIXING INSTRUCTIONS | PER 500 GAL TANKS

CLAY COMMANDER	1 TUB
HDD LUBE	1 JUG
ADD BORE COMMANDER	1/2 JUG
IF NEEDED FOR VISCOSITY	

ALTERNATIVE MIXING INSTRUCTIONS:

SODA ASH	2 POUNDS
MAXBORE OR MAXGEL	1 1/2 - 2 BAGS
SAND FORCE	2 POUNDS
PAC L FORCE	2 POUNDS
HDD LUBE	1 JUG

* IF NEEDED FOR REACTIVE CLAY: 1 JUG OF CLAY BOMB
* ADD CLAY BOMB & HDD LUBE AFTER BENTONITE IS YIELDED.

TOOLING:

MIX MASTER

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



ROCK/GRAVEL/SANDSTONE

GENERAL MIXING INSTRUCTIONS | PER 500 GAL TANKS

SODA ASH	2 POUNDS
MAX BORE OR GEL	2-3 BAGS
COBBLE COMMANDER	1 TUB
HDD LUBE	1 JUG

IF HEALTHIER FILTER

CAKE IS NEEDED FOR

FLUID LOSS:

PAC L FORCE	1-2 POUNDS
-------------	------------

TOOLING:

FLUTED REAMER

STACKED PLATE REAMER

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



SIMPLE SOLUTIONS KEEP YOU TURNING TO THE RIGHT.

RIGHTTURNSUPPLY.COM | 641.204.0205

in @ d f