



RIGHT TURN SUPPLY

LIQUID MUD CHART

PRODUCT BREAKDOWN



SAND

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

SAND GRENADE XL	1-2 JUGS
HDD LUBE	1 JUG

TOOLING:

FLUTED REAMER

FLYCUTTER

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



CLAY/REACTIVE CLAY

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

BORE COMMANDER	1 JUG
CLAY BOMB	1-2 JUGS
DET CON 1	1 JUG

TOOLING:

MIX MASTER

BEAVER TAIL

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



ROCK/GRAVEL/SANDSTONE

GENERAL MIXING INSTRUCTIONS | PER 500 GAL

SAND GRENADE XL	1-2 JUGS
HDD LUBE	1 JUG

TOOLING:

FLUTED REAMER

STACKED PLATE REAMER

* LIQUIDS THROUGH TOP OF TANK AND DRY PRODUCTS THROUGH THE HOPPER. ADDITIONALLY, MIXED ALL DRY PRODUCTS BEFORE LIQUIDS.



SIMPLE SOLUTIONS KEEP YOU TURNING TO THE **RIGHT.**

RIGHTTURNSUPPLY.COM | 641.204.0205

in @ d f